

Safety instructions and technical specifications

Disclaimer The illustrations in this document may deviate from the delivered product. We reserve the right to make changes due to errors or based on technical advances. A word on copyright This document is proprietary and was originally written in German. Its reproduction and distribution in whole or in individual parts without permission of the copyright owner is prohibited and will be prosecuted under criminal or civil law. All rights reserved, including for translation.

Copyright by INDEX-Werke GmbH & Co. KG



1 I	Explanation of symbols	(
1.1	Symbols in the user documentation	(
1.2	Information and safety instructions on the machine	
2 (General information on safe operation	8
2.1	Obligations of the operator/owner	
2.2	Personnel obligations	
2.3	Requirements for personnel selection and qualifications	
	2.3.1 Definition of "qualified employee"/"qualified personnel"	
	2.3.2 Personal selection and qualifications	
2.4	Intended use of the machine	1
2.5	Reasonably foreseeable misuse of the machine	1
2.6	Modifications to the machine	1
2.7	Spare parts and accessories	1
2.8	Repairs	1
2.9	Workplace of the operator	13
	2.9.1 Physical locations at the workplace	1
2.10	0 Personal protective equipment	1:
2.11	1 Climbing aids	1
2.12	2 IT and data security	1
3 \$	Safety functions and safety devices	
3.1	Main switch	
3.2	• , ,	
3.3		
	3.3.1 Automatic work area door—fast travel	
3.4	Safety glass	1
3.5	Shatter protection film on the work area door with acrylic glass elements	1
3.6	Clamping conditions	1
3.7	Pneumatic safety valve (optional)	1
3.8	Warning signals/indicators	1
3.9	Keys and password protection	1
3.10	0 Consent function	1
3.11	1 Pressure vessels	1
4 I	Instructions for safety-conscious work	2
4.1	Handling of workpieces	2
	4.1.1 Clamping workpieces	2
	4.1.2 Clamping pressure and clamping force	2
	4.1.3 Chuck and jaws	2
	4.1.4 Machining of bar stock	2
4.2	Handling of tools	2

INDEX

	4.2.1 Changing tools	22
	4.2.2 Mechanical interface	23
4.3	Chip conveyor	23
	4.3.1 Machine without chip conveyor	24
4.4	Work on electrical components	24
4.5	Prevention of burns and scalds	25
4.6	Conduct around noise	25
4.7	Conduct around laser radiation	25
4.8	Handling of operating fluids	25
5 F	Fire protection	27
5.1	Fire risks	27
	5.1.1 Combustible working materials and by-products	
	5.1.2 Minimal quantity lubrication system or dry machining	
	5.1.3 Combustible cooling lubricants	
5.2	General fire safety measures	
	5.2.1 Use of CO₂ as an extinguishing agent	
5.3	Fire extinguishing system for cooling lubricant fires	28
	5.3.1 Intended use of the fire extinguishing system	28
	5.3.2 Foreseeable misuse of the fire extinguishing system	
5.4	Central extraction system	29
6 9	Safety instructions for different life phases	30
6.1	Transport and packing	30
6.2	Setup, installation, and commissioning	30
	6.2.1 Electrical hazard due to potential difference	31
6.3	Setup mode	31
6.4	Operation (production mode)	31
6.5	Maintenance, service, and repair	32
6.6	Storage and decommissioning	33
6.7	Disposal	33
7 F	Product monitoring	34
8 [Declaration of conformity	35
9 1	Fechnical specifications	36
9.1	Approved ambient conditions	36
9.2	Floor condition	36
9.3	Noise emission	36
	Safety instructions for machining workpieces and machining technologies	
10.1	I Use and operation of clamping devices on the main and counter spindles	38

Table of contents

INDEX

10.2 Use of tools in the motorized milling spindle	39
10.3 Specific and individual single applications (of tools)	39
10.4 Workpiece clamping with live center to improve workpiece quality	39
10.5 Safe workpiece clamping using the tailstock or tailstock function	40
10.6 Workpiece clamping with a steady rest to improve workpiece quality	40
10.7 Safe workpiece clamping with steady rest	41
10.8 Use of clamping devices with several workpiece clamping options on main and counter spindles	41

DAA007EN - 2025-03-03 5 / 42



1 Explanation of symbols

1.1 Symbols in the user documentation

This chapter explains the symbols used throughout the user documentation to indicate hazards and provide helpful guidance.

A DANGER



This symbol indicates an immediate danger to life and health.

Failure to observe this warning will result in serious injury or death.

• Follow the specified safety instructions.

MARNING



This symbol indicates a potential danger to life and health.

Failure to observe this warning may result in serious injury or death.

• Follow the specified safety instructions.

A CAUTION



This symbol indicates a potential health hazard.

Failure to observe this warning may result in injury or harm to health.

• Follow the specified safety instructions.

NOTICE



This symbol indicates important notes for the proper operation of the machine.

Failure to observe this information may result in damage to or malfunction of the machine.

• Follow the specified safety instructions.



Helpful tips and information.



• Reference to other documents.

DAA007EN - 2025-03-03 6 / 42



1.2 Information and safety instructions on the machine

All information and safety instructions directly on the machine must be observed and must be kept in a fully legible condition.

Various symbols and warnings may be found on the machine, depending on the design of the machine and its intended use.

DAA007EN - 2025-03-03 7 / 42



2 General information on safe operation

2.1 Obligations of the operator/owner

The operator/owner must ensure that all the specified limits, ambient conditions, and clearances in the vicinity of the machine are observed at the place of installation.

Prior to commencing operation of the machine:

- The operator must understand the dialog language of the control system user interface.
- The personnel responsible must be sufficiently qualified to perform the work assigned to them. This applies particularly to commissioning, maintenance, and servicing, as well as any work on electrical systems and components.
- All safety equipment must be properly installed and functional; it must not be tampered with or disabled.
- Devices and measures to override the restricted access to the controller (e.g., keys for switches, passwords) must be accessible only by authorized personnel.
- The machine must be in proper functional condition. Any damaged or defective parts must be replaced immediately. This applies particularly to all safety equipment.

2.2 Personnel obligations

The personnel responsible must read and understand the user documentation, including the caution labels. This applies particularly to the safety labels and warnings.

All individuals who operate or work on the machine are obligated to ensure the following before beginning work:

- All fundamental occupational safety and accident prevention regulations must be observed.
- The safety chapter and all warnings in the user documentation must be followed. Relevant sections must be read or explained to personnel as needed.

All those carrying out work on the machine must use the required personal protective equipment.

2.3 Requirements for personnel selection and qualifications

2.3.1 Definition of "qualified employee"/"qualified personnel"

A qualified employee is capable, on the basis of their relevant professional education, training, and/or experience, to recognize risks and to avoid possible hazards that arise when using the product.

Depending on the activities to be carried out, these qualified employees may be from various fields, e.g., qualified transport personnel for transport or qualified electricians for work on the electrical equipment of a product.

2.3.2 Personal selection and qualifications

The personnel responsible must be sufficiently qualified to perform the work assigned to them. Individuals undergoing training must not work on the machine without constant supervision by a person having the required qualifications.

Qualified personnel must meet the following requirements:

DAA007EN - 2025-03-03 8 / 42



Transport personnel

Qualified employees/trained individuals with knowledge of the relevant load securing and approval for the means of transport of the relevant type

Installation/commissioning personnel

 Qualified employees/technically trained individuals with experience in installing and commissioning machines of this type

Setup personnel

- Trained and qualified employees
- Specialized training by the manufacturer

Programming personnel

- Trained and qualified employees
- Specialized training for the machine or programming system by the machine manufacturer

Operating personnel

- Trained skilled employees or semi-skilled employees
- Comprehensive instruction on the machine
- Operator training by the manufacturer

Maintenance personnel

- Trained skilled employees or semi-skilled employees
- Specialized training by the manufacturer

Service and repair personnel

- Trained and qualified employees
- Specialized training by the manufacturer

Decommissioning/storage personnel

• Trained and qualified employees

Disposal personnel

• Trained and qualified employees

Expert

A person who has sufficient knowledge of the machine based on professional training and experience and who is familiar with all regulations, thereby enabling evaluation of the inspected machine with regard to occupational safety.

DAA007EN - 2025-03-03 9 / 42



The following also applies:

- Work on the machine may only be carried out by reliable persons who are able to cope with the physical demands involved.
- Key switches may only be operated by instructed and authorized persons. The key must be removed after use and stored in such a way that unauthorized persons do not have access.
- Work on the electrical equipment of may only be carried out by qualified electricians or by instructed persons under the direction and supervision of a qualified electrician in accordance with the electrical/electronic regulations.
- Work on the hydraulic system may only be carried out by trained and authorized persons.
- Potentiometer and switch settings, parameters, etc., may only be changed by the manufacturer's service personnel.

2.4 Intended use of the machine

The intended use of the machine and the additional components must be observed and complied with.

A DANGER

Risk of injury or death



Exceeding the specified dimensions or limits of workpieces, clamping devices, tools, operating fluids, or additional components may result in serious injury.

 The specified limits for the machine and any additional components must never be exceeded.

The machine has been designed mainly for cold working of common metallic materials without requiring access to the work area during machining.

The machine is intended exclusively for use in industrial environments and for commercial use.

The machine has been designed and constructed in accordance with current best practices and generally recognized safety rules. All the required safety equipment and protective apparatus are present.

The operational safety of the machine is only ensured if it is used as intended.

If it is not used as intended, risks may arise.

Residual risks exist even when the machine is used as intended.

The limits specified in the technical data (e.g., maximum rotational speed or maximum turning length) must be observed.

The maximum permissible pressure for non-water-miscible cooling lubricants is:

- for single-spindle turning machines: 120 bar
- for multi-spindle turning machines: 80 bar

The machine must not be operated in an explosive atmosphere.

Only one person at a time may work on the machine.

DAA007EN - 2025-03-03 10 / 42



If more than one person is required in exceptional cases, the operator/owner must appoint one person as the person responsible for coordinating the work and complying with the occupational safety regulations.

Do not walk on the machine or its auxiliary units.

If, in exceptional cases, it is necessary to be on the machine, this is expressly permitted only when the machine is switched off.

The safety notices and warnings in the operating instructions and on the machine must be observed.

All the safety notices and warnings on the machine must be kept in a legible condition and must be replaced if necessary.

2.5 Reasonably foreseeable misuse of the machine

Reasonably foreseeable misuse includes:

- Bypassing protective apparatus during operation
- Operating the machine in ambient conditions other than the approved ambient conditions

Machining of the following materials is not permitted:

- Explosives
- Materials releasing hazardous substances during the machining process (e.g., toxic or radioactive substances)
- Materials that produce explosive dusts during machining
- Combustible materials
 This does not apply to titanium alloys if appropriate fire-safety measures are met when dealing with the collection of chips.
- Materials without sufficient inherent stability

2.6 Modifications to the machine

Modifications to the machine may result in a safety risk. This applies particularly to all safety equipment, electrical circuits, and the machine control system software and parameters.

Significant modifications to the machine may lead to non-conformance with the applicable directives for product safety.

Therefore, the operator/owner must not make any modifications or additions to the hardware or software of the machine without the written approval of INDEX-Werke GmbH & Co. KG.

Modifications approved by the manufacturer must be documented in a traceable manner.

2.7 Spare parts and accessories

The use of unapproved products may change the structural characteristics of the machine and negatively affect its active or passive safety.

The use of original spare parts and accessories is recommended. For damage caused by the use of parts from third-party providers, liability and warranty are excluded.

If you have any questions or doubts, contact INDEX-Werke GmbH & Co. KG. This may help prevent more serious damage.

DAA007EN - 2025-03-03 11 / 42



2.8 Repairs

The operator/owner's employees may only carry out maintenance and repair work to the extent described in the user documentation. The instructions for it must be followed in all particulars.

INDEX-Werke GmbH & Co. KG assumes no liability or warranty for damage and operational malfunctions as a result of non-compliance with these instructions or improper repairs by the operator/owner's personnel.

If you have any questions or doubts, contact INDEX-Werke GmbH & Co. KG. This may help prevent more serious damage.

The information and instructions in this document and in the accompanying technical documents must be observed.

2.9 Workplace of the operator

It is recommended that a working area of at least 1 m is kept free around the machine (including attached units) for operator activities.

Workplaces can vary depending on the activity.

The following activities, among others, can occur during production:

- Operating the machine from the operating terminal
- Loading and unloading workpieces
- Refilling bar stock in the bar loading magazine, if one is present
- Removing chips in the work area and on the chip conveyor, as needed
- · Emptying the chip container
- Observing and maintaining the process at the operating terminal and in the work area
- Removing and measuring workpieces
- Checking operating fluids (such as hydraulic fluid, lubricant, cooling lubricant) and refilling if necessary
- Changing tools on the tool magazine or in the work area
- If needed: making adjustments for tool wear in the machine control system

A different workplace may apply during the following activities:

- In setup mode
- Inspection and testing
- · Cleaning work
- Maintenance work

2.9.1 Physical locations at the workplace




Illustration 1: Physical locations of a single-spindle turning machine, example

DAA007EN - 2025-03-03 12 / 42






Illustration 2: Physical locations of a multi-spindle turning machine, example




Illustration 3: Physical locations of a sliding headstock turning machine, example

2.10 Personal protective equipment

The operator/owner must provide personal protective equipment.

The operator/owner's safety representative should be consulted regarding the use of personal protective equipment.

Personal protective equipment required depending on the specific activity:

- · close-fitting workwear
- safety shoes
- safety goggles (suitable eye protection)
- hairnet
- · safety helmet
- · safety gloves
- hearing protection
- skin barrier cream

Additional personal protective equipment required if combustible operating fluids are used:

• flame-retardant work clothes

MARNING



Risk of injury from flammable operating fluids

Work clothing may catch fire.

• Contaminated clothing must be removed immediately.

DAA007EN - 2025-03-03 13 / 42



2.11 Climbing aids

If climbing aids (ladders or steps) are used to carry out certain activities, be sure to observe the safety regulations and instructions for the intended use published by the respective manufacturer.

2.12 IT and data security

Direct access to the production network should be protected by a firewall and hence according to the current IT security standards. Nevertheless, it is the operator/owner's responsibility to verify that the measures taken in the existing network are sufficient.

External data storage media, as well as maintenance and service devices, represent basic security risks. These devices should be scanned for viruses before they are used.

Only software that is required for production is installed on the controller. Installation of additional software is not permitted.

Only network connections that are necessary, secure, and have been selected for the production process (e.g., for remote maintenance) may be set up on the controller. Unrestricted Internet access to the controller must be prevented.

Additional protection can be achieved by network segmentation (e.g., by separating the production network from the office network) to prevent mutual interference.

Modifications to the operating system are not permitted.

DAA007EN - 2025-03-03 14 / 42



3 Safety functions and safety devices

Some machine components, aside from their technical functions, also fulfill a safety function that is designed to protect personnel from dangers at the machine.

For this reason, safety functions must not be tampered with, disabled, or removed.

In case of damage to or failure of safety functions or equipment, the machine must be shut down immediately.

Removal of safety functions is only allowed during repair work on the machine. Once the repairs are finished, all safety equipment must be reinstalled and checked for proper functioning.

3.1 Main switch





Illustration 4: Main switch, example

Turning the main switch to the "O" position (OFF) switches off the power supply.

⚠ DANGER

Risk of electric shock

Electrical components marked accordingly may remain live even when the main switch is switched off and can be potentially lethal if not handled properly.



- Before carrying out any installation or repair work, switch off the relevant area switches and secure them against being switched on again.
- Before all installation and repair work, if applicable, remove the relevant fuses.
- Observe the machine's electrical documentation.

The main switch can be secured with a safety lock to prevent it from being switched back on without authorization.

3.2 Emergency stop



Illustration 5: Emergency stop device, example

Emergency stop devices are located at every operator position and should be actuated when human life is in danger.

When actuated, all hazardous movements are switched off as quickly as possible, and a safe state is established. However, the machine is not disconnected from the power supply. A fault message is displayed on the screen.

DAA007EN - 2025-03-03 15 / 42



Unlocking the emergency stop does not cause the machine to restart automatically.

MARNING

Risk of injury or death



Blocked access to an emergency stop device may prevent hazardous movements from being stopped in an emergency.

 Ensure the emergency stop devices are accessible and visible at all times.

3.3 Work area enclosure and work area door

The work area enclosure and work area door constitute guards.

During the setup and production of workpieces, it is possible for machine parts or workpieces to accidentally come loose and be thrown around.

If this happens, the guard protects the personnel at the machine against dangers resulting from this situation. For this reason, no modifications may be made to the guard.

The specified impact resistance of the guard must be observed. Detailed specifications for the resistance classes can be found in the applicable standards. The impact resistance is rated based on the forces expected, but it may be exceeded due to special process parameters.

This applies, in particular, when specially adapted clamping devices are used. For the selection and adaptation of clamping devices not provided as standard, the technical limits and impact resistance of the machine and the instructions for the clamping devices must be observed.

The protective measures were implemented according to the applicable type C standard for the machine, although a residual risk always remains.

The work area enclosure at least complies with the normative specifications but usually significantly exceeds them. Nevertheless, when operating the machine, it should be noted that the standard impact resistance covers, at most, the loss of a jaw fragment or a single jaw.

There are physical limits to the impact resistance against larger bodies.

MARNING

Risk of injury or death



The work area enclosure may be deformed or penetrated if entire workpieces, tools, or other bodies are thrown against it.

- During production, always maintain a distance of 20 cm from the work area door, which must always be closed.
- Signs on the machine must be observed.

In setup mode, the possible movements are severely restricted (e.g., by reduced axis speeds) when the work area door is open.

The interlock on the work area door must not be tampered with or disabled.

DAA007EN - 2025-03-03 16 / 42



3.3.1 Automatic work area door—fast travel

During the **automatic** loading and unloading of the machine, the "fast travel of the automatic work area door" function can be activated. This temporarily overrides force monitoring and obstacle detection.

To prevent access to the movement of the work area door, the complete range of movement of the work area door must be secured.

This can be realized by:

- Complete enclosure of the movement area of the automatic work area door by a protective fence
- Partial enclosure of the movement area of the automatic work area door by a protective fence with supplementary contactless protective devices (light barriers, area scanners,...)

For the afterrun time of the entire "automatic work area door" system, t=1s can be assumed.

A CAUTION

Risk of injury from movement of the automatic work area door with "fast travel" function



Injuries may occur if minimum safety distances are not observed.

- Safety distances must be maintained, and any afterrun or access times must be taken into account.
- The protection of the hazardous area must be designed according to the requirements.

Disclaimer



The entity placing the machinery on the market (in accordance with the Machinery Directive) is responsible for ensuring that the safety distances comply with the standards and that the minimum requirements for the safety functions are met.

3.4 Safety glass

The work area door is equipped with safety glass panes. These panes have the required resistance class and provide:

- A view of the machining process
- Protection from objects that may be thrown out, e.g., chips, tools, or broken-off parts of workpieces
- Protection from splashed coolant

DAA007EN - 2025-03-03 17 / 42



The safety glass pane of the work area door complies at least with the normative specifications but usually significantly exceeds them.

Nevertheless, when operating the machine, it should be noted that in reaction to a collision against the glass pane, the pane will plastically deform (even without a puncture) to dissipate the collision energy.

MARNING

Risk of injury or death



In the event of a collision against the safety glass pane, it can deform outwards by up to 20 cm.

If the safety glass pane is too close, there is a risk of serious injury (even without a puncture)!

 During production, always maintain a distance of 20 cm from the work area door, which must always be closed.

The safety glass pane must be checked for damage, such as cracks, in accordance with the maintenance instructions.

The safety glass panes must be replaced every time they are damaged (e.g., if they become cloudy or cracked) because their protective effect is no longer guaranteed.

The year of manufacture is indicated on the safety glass pane. When the interval specified in the maintenance instructions expires, the safety glass panes must be replaced, even if they are not damaged.

3.5 Shatter protection film on the work area door with acrylic glass elements

For additional safety, a special high-transparency shatter protection film is affixed to the exterior of the work area door with acrylic glass elements. ¹



Never remove the shatter protection film.

3.6 Clamping conditions

A description of clamping stroke monitoring is included in the respective user documentation.

The monitoring measures designed to ensure the clamping conditions (e.g., clamping stroke monitoring, clamping pressure monitoring) must not be bypassed.

3.7 Pneumatic safety valve (optional)

If compressed air is used in the machine, it is equipped with the following:

- A compressed air maintenance unit with pressure control valve, including a pressure gauge to display system pressure (used to set the operating pressure)
- An electric on/off valve
- A manual on/off valve to isolate the machine from the air supply (customer-provided line)

A system pressure sensor to monitor the customer's network is also installed.

DAA007EN - 2025-03-03 18 / 42

Some machine types use two layers of shatter protection film.



3.8 Warning signals/indicators

Various indications, alerts, and messages are displayed on the screen. They are usually self-explanatory.

The machine status is signaled by a multi-indicator lamp.

3.9 Keys and password protection

Access to the various operating modes and settings is protected using keys and passwords.

Do not allow keys or passwords to come into the hands of unauthorized persons.

Setup mode is safeguarded by a key.

The key must be pulled out again once setup mode is finished.

Programs and other safety-related settings can only be accessed after entering the corresponding passwords. The passwords are linked to a number of protection levels. The protection levels available are determined by the customer's requirements and the configuration used by the manufacturer.

3.10 Consent function

In setup mode, with the work area door open, hazardous movements can only be started when both the Confirmation key and the Action key are pressed. If one of the keys is released, the movement is stopped.

3.11 Pressure vessels

Depending on the classification in the pressure equipment directive, the hydraulic accumulator (in a pressure vessel system) is either a system part requiring monitoring or an item of equipment.



The machine owner/operator is obligated to comply with and meet the current Industrial Safety Regulations.

The guidelines and regulations applicable in the country of use must be followed. Contact the relevant approval authority if you have questions.

According to applicable regulations, defective pressure accumulators must be depressurized and disposed of by an authorized and qualified employee.

The pressure accumulator must be replaced as specified in the user manual of the manufacturer.

⚠ WARNING

Risk of injury



Maintenance work on fluid systems (hydraulic, lubrication, and pneumatic systems) may involve a risk of injury.

Before starting any work, ensure the relevant system has been depressurised (accumulator drain valve/manual slide valve).

DAA007EN - 2025-03-03 19 / 42



4 Instructions for safety-conscious work



All specifications in the user documentation as well as the applicable directives and regulations must always be observed. For integrated components made by third parties, the user documentation of the respective manufacturers must be observed as well.

4.1 Handling of workpieces

4.1.1 Clamping workpieces

The clamping system forms the interface between the machine and the workpiece and serves to absorb the forces occurring during the machining process. For this reason, the clamping system is of particular importance.

The shape and mass of the machined workpiece before, during, and after machining is vitally important. Therefore, workpieces must have a balanced mass. For unbalanced workpieces, the clamping device must be adapted appropriately. In the case of shape-related unstable workpiece clamping (e.g., with long, thin parts), there is also a risk of buckling. Appropriate measures must be taken to prevent this.

In general:

- Only clamping devices that have been approved by the machine manufacturer may be used. When in doubt, the machine or clamping device manufacturer should be consulted.
- The clamping device must be dimensioned and used according to the specifications in the (third-party manufacturer's) user documentation and applicable directives.
- All components of the clamping system must be maintained in proper and functional condition.
- The maximum permitted rotational speed must be limited. In this regard, the lowest permissible rotational speed of all components involved (clamping device or workpiece) determines the maximum permitted rotational speed. The rotational speed limits must be stored in the controller and written into the machining program.
- When using chucks (jaw chucks), the maximum permissible speed must be calculated (taking into account the resistance class of the respective machine).



It is recommended that the maximum permissible speed always be calculated using the software (calculation aid for speed limitation) stored in the controller. The respective resistance class of the machine is stored in the software.

The specifications in the applicable user documentation must be observed.

- The prescribed rotational speeds must be adhered to.
- Components of the clamping system may only be modified after consultation with the machine manufacturer.
- Remove chips only with suitable auxiliary equipment.

4.1.2 Clamping pressure and clamping force

n

The clamping system manufacturer's information must be observed.

The clamping device must be cleaned, lubricated, and maintained regularly.

DAA007EN - 2025-03-03 20 / 42



The required clamping force must be determined based on applicable directives and regulations. The nominal actuation force shown in the diagrams is converted by the clamping device into the actual clamping force.

The required clamping force is set via the pressure/spring preload on the clamping cylinder.

However, the set clamping pressure does not give a direct indication of the actual clamping force. Therefore, the actual clamping force must be determined by clamping force measurement.

Regular tension force measurements provide information about their change over time and the measures to be derived from them.

The actual clamping force varies due to:

- speed-related centrifugal forces
- friction at the mechanical contact points
- friction at various sealing points
- contamination
- the service life of the clamping device
- the materials machined in the machine
- the cooling lubricants used
- the working mechanisms with transmission ratio in the clamping device
- the maintenance condition.

Depending on the workpiece (e.g., in the case of highly unbalanced parts or special clamping jaws), operating conditions may deviate from the rule. This may change the permitted rotational speed, chuck actuating forces, and other characteristics required for safely clamping the workpiece.

4.1.3 Chuck and jaws


When a workpiece is placed in a chuck, there is a risk that fingers will be crushed between the jaws and the part.

In general:

- The original mounting means of the clamping device manufacturer must be used to mount the jaws.
- Mounting screws of the maximum possible length must be used.
- The mounting screws must be tightened with a torque spanner. The torque must be selected according to the strength class of the screws or in conformity with the specifications of the clamping device manufacturer.
- Distance A (refer to drawing) between the end of the screw and the end of the thread must not exceed 2 mm.
- Distance B (refer to drawing) must be as large as possible.
- Jaws with a maximum permissible rotational speed that is less than that of the clamping device or the spindle must be marked in a clearly visible manner (e.g., with the maximum permissible rotational speed).
- The jaw stroke of each jaw must not exceed 4 mm. It must be ensured that the jaws are shaped accordingly.
- Manual loading and unloading in automatic mode is not allowed. For manual loading and unloading with clamping strokes > 4 mm, appropriate safety measures must be taken.

DAA007EN - 2025-03-03 21 / 42





- 1 Workpiece
- 2 Top jaw
- 3 Mounting screw

- 4 Base jaw
- 5 Chuck body

4.1.4 Machining of bar stock

The following always applies to the machining of bar stock:

- The spindle clearance must be adjusted to the diameter and profile of the bar stock (e.g., with reducing sleeves).
- Bar stock must not protrude beyond the end of the spindle. The following must be observed when machining bar stock:
 - Bar stock may only be machined in combination with a bar guide or bar feeder. If no bar feeder is used, the opening in the enclosure provided for this purpose must be closed.
 - Manual loading of short bars is only permitted if this is carried out through a secured feed opening on the machine side. INDEX offers suitable solutions for this. The machine-specific max. dimensions of the bar stock must be observed.

4.2 Handling of tools

4.2.1 Changing tools

When tools are changed, there is a risk of injury from protruding and sharp-edged tools.

In general:

- Suitable personal protective equipment must be used.
- Tool carriers must be moved to an ergonomically convenient position.
- Suitable protective measures be taken (e.g., cloth or protective sleeves) for protruding tools (e.g., boring bars).
- Suitable tools (e.g., torque spanner with extension) must be used.
- The required torque must be observed. The relevant specifications can be found in the data sheets of the tool holders.
- When using laser systems for tool monitoring, avoid looking directly into the laser source.
- For live tools and tool holders, the maximum permitted rotational speed and corresponding balance quality must be maintained.

DAA007EN - 2025-03-03 22 / 42





4.2.2 Mechanical interface

Use only tools and tool holders that are designed for the corresponding mechanical interface and match the technical data of the tool mounting. The operator/owner is responsible for the correct installation of the tools or tool holders.

4.3 Chip conveyor

The chips resulting from the machining are transported by a chip conveyor from the work area to a collection bin. The chip conveyor has a conveyor belt that transports the chips sideways and upward, so they can be dropped into the collection bin. The chip conveyor does not transport the chips continuously out of the work area but at (adjustable) intervals.

The staff at the machine is not able to see when the chip conveyor starts the transport operation. This results in an increased risk of injury in conjunction with a variety of possible crushing or shearing points in the work area of the machine and at the discharge point of chips.

Walking on the chip conveyor is always forbidden.

DAA007EN - 2025-03-03 23 / 42



To avoid injury of the staff at the machine, the following measures have been taken:

- The movement of the chip conveyor is disabled when the work area door is open. Backward movement in jog mode is possible in combination with the confirm key.
- At the beginning of each conveying interval, the conveyor belt moves only a small distance. This so-called start-up motion is to warn the staff at the machine of the imminent start of the conveyor belt in order to allow them to leave the danger zone.
- If a discharge chute is fitted at the chip conveyor's drop-off point that prevents direct access to a hazardous area, the chute may only be removed if access is prevented by other means (e.g., a cover with an opening precisely matched to the discharge point).
- The chip conveyor has a button at the discharge chute, by which the running direction of the conveyor belt can be reversed. This allows the operator to remove
 accumulated chips clogging the transport chute without dismantling the discharge
 chute or other covers.

4.3.1 Machine without chip conveyor

Before commissioning a machine without a chip conveyor (e.g., with centralized chip removal), the operator/owner must provide a safe and environmentally friendly option for chip removal.

When operating a machine without a chip conveyor, hazards arise at the mechanical interface.

Possible hazards due to the opening:

- In the event of a fault, parts may be thrown out through the chip conveyor opening (clamping jaws, workpieces, remnants, etc.).
- Breathing difficulties or asphyxiation due to escaping extinguishing gas
- Hot and sharp-edged chips
- Cooling lubricant coming out (possibly under high pressure)
- Slipping/falling on leaked cooling lubricant
- Flames coming out

In the case of centralized chip disposal and machining with oil:

• Flames coming out through the gap or into the centralized delivery. Remedy: apply a seal so that there is no gap.

4.4 Work on electrical components

▲ DANGER

Improper work on the electrical system

Improper practices when working on the electrical equipment of the machine may result in death or serious injury.



- The intended use of the machine and the additional components must be observed and complied with.
- All work on the electrical equipment must be carried out exclusively by properly trained and instructed qualified personnel.

All information in the circuit diagrams must be observed.

DAA007EN - 2025-03-03 24 / 42



Prior to commencing any work on the electrical equipment, the main switch must be switched off and locked out. To avoid damages to the machine, the prescribed power on/off sequence of the machine must be observed.

Electrical components may carry electric energy even after the machine has been switched off. These components are labeled and must not be touched before the specified discharging time has elapsed.

Some electrical components of the machine generate high voltages (e.g., power modules of the drives in the control cabinet). Any work on these components must be carried out with utmost care, as any mistakes in this respect may result directly in death.

Electrical components may only be replaced with components having identical ratings.

After finishing work on electrical assemblies, the electrical equipment must be inspected by qualified personnel. In particular, it must be ensured that all the required protective covers have been attached correctly.

Prior to switching on the machine, all doors to electrical installation spaces must be closed and secured against unauthorized access.

In case of a power failure, the main switch must be switched off and locked out. The machine may only be switched back on after the power system has been restored.

4.5 Prevention of burns and scalds

Before starting work on the machine, disconnect it safely from the power supply, depressurize it, and allow it to cool down, as operating fluid may heat up and parts located under covers may be hot.

If necessary, use suitable protective gloves for heated parts.

4.6 Conduct around noise

Noise emitted from the machine is measured according to the applicable directives and regulations. For details of noise emission values, see the chapter **Technical specifications** [**36**].

The actual noise emission at the machine depends on the production process and the ambient conditions at the place of installation.

Noise can cause hearing loss. Wear hearing protection if needed.

4.7 Conduct around laser radiation

Laser-based systems may be used on the machine. The lasers used, at maximum intensity, conform to Class 2 (according to DIN EN 60825).

Caution signs are posted around the usage site of the lasers, warning against directly looking into the laser beam to avoid burns (particularly of the retina) due to laser radiation.

4.8 Handling of operating fluids

For all work in connection with operating fluids the information in the data sheets of the respective manufacturers and the information in the document "Information on operating fluids" must be followed.

The required quantities of operating fluids can be obtained from the relevant fluid plans.

DAA007EN - 2025-03-03 25 / 42



The following generally applies when handling operating fluids:

- Leaked or spilled liquids must be removed immediately to prevent people from slipping, stumbling, or falling.
- Filling aids (e.g., funnels) must be used for adding fluids.
- Skin contact with lubricants and cooling lubricants must be avoided.
- The manufacturers' material safety data sheets and instructions for use must be observed.
- Personal protective equipment must be used.
- Operating fluids must be disposed of in a safe and environmentally friendly way.
- The specifications in the user documentation for operating fluids must be observed.

Machining may cause emissions (dust, gases, or cooling lubricant vapors) that require a mist extractor.

A mist extractor is optionally available and can be obtained—together with the machine—from INDEX. The defined interface to the exhaust system is to be used.

Follow the supplier documentation and the drawing provided.

DAA007EN - 2025-03-03 26 / 42



5 Fire protection

5.1 Fire risks

The operator/owner is generally responsible for preventing flash fires or open fires.

The operator/owner should establish the required measures in consultation with the appropriate bodies (e.g., occupational health and safety organizations, fire safety engineer, fire brigade).

High heat generation, open fire, or other ignition sources (e.g., cigarettes) in the vicinity of the machine are prohibited.

An elevated risk of fire may arise in the following cases.

5.1.1 Combustible working materials and by-products

To combat fires caused by flammable materials, especially fine chips (e.g., titanium), appropriate fire protection measures must be taken.

5.1.2 Minimal quantity lubrication system or dry machining

Using a minimal quantity lubrication system or dry machining poses a potential fire

Therefore, such a system may only be used after consulting the manufacturer. In this case, it must be checked what other equipment (e.g., a mist extractor) is required for the safe operation of the machine.

5.1.3 Combustible cooling lubricants

The use of some cooling lubricants in combination with certain manufacturing parameters and the material to be machined poses an increased risk of deflagration and fire.

As this puts the personnel at the machine at an elevated risk, suitable precautions must be taken to prevent deflagration and fires.

Sufficient cooling must be ensured during the entire machining process in order to prevent sparking. The cooling lubricant must be checked at regular intervals, and its correct fill level must be maintained.

The machine must be operated under supervision when using combustible cooling lubricants. A machine is considered to be sufficiently supervised if, for example, a person is present who can perceive the machine's fire extinguishing system's audible and visual alerts, or if activation of the fire extinguishing system is transmitted to a central monitoring location (e.g., a control center, fire department, etc.) and appropriate action can be taken on-site in response.

The use of a fire extinguishing system is recommended when using water-based cooling lubricant with an oil content greater than 15% or cutting oil based on mineral oil.

5.2 General fire safety measures

The operator/owner is responsible for following the applicable regulations and directives for fire safety and for training the personnel for an emergency.

A fire extinguishing system does not relieve the operator/owner from the usual preventive or defensive measures in case of fires. This applies to the entire environment of the machine, in particular, also above the machine.

Despite all technical protection measures, the exit of flames can not be entirely ruled out. Therefore, there is a residual risk for the personnel at the machine.

DAA007EN - 2025-03-03 27 / 42



No permanent workplace may be in the vicinity of potential flame exit points on the machine (e.g., a table for cleaning workpieces).

Personnel should avoid being in the vicinity of potential flame exit points as much as possible.

A fire protection assessment of the structural conditions of the installation site must be carried out by the machine operator/owner.

The following always applies in the event of a fire:

- If a warning signal (e.g., signal horn) sounds, leave the danger area or the room immediately; the personnel must be instructed accordingly for this purpose.
- Access to the room or area where the fire event took place may only be granted
 after this has been approved by an authorized person (e.g., fire safety engineer,
 fire insurance company, fire department).

Depending on the structural conditions, the term "room" or "area" is to be understood flexibly between an enclosed area with access doors and the direct environment of the work area the hazard may affect. A corresponding definition is to be made after evaluating the residual hazard by the machine operator/owner.

5.2.1 Use of CO₂ as an extinguishing agent

The extinguishing effect of CO₂ is based on reducing the oxygen in the air below the concentration required for combustion.

A DANGER

Health and life hazard



A CO_2 concentration of more than 5% in the surrounding area poses a serious risk to health and life. This must be observed especially if the extinguishing gas is able to flow into spaces at a lower level.

- Exit the hazard area immediately!
- Pay attention to room volume when installing the machine. This is the operator/owner's responsibility.

A safety zone of 10 $\rm m^3$ of room volume per kg of $\rm CO_2$ must be available around the machine. This ensures that the extinguishing gas can disperse safely after being released from the machine.

This corresponds to a room volume of 60 m^3 for a 6 kg CO_2 compact fire extinguishing system, and 300 m^3 for a 30 kg CO_2 fire extinguishing system.

5.3 Fire extinguishing system for cooling lubricant fires

After consultation with the customer, INDEX-Werke GmbH & Co. KG will equip machines with a fire extinguishing system to extinguish cooling lubricant fires if this is required for the machine's expected use.

5.3.1 Intended use of the fire extinguishing system

The fire extinguishing system is intended only for detecting and extinguishing cooling lubricant fires within the machine's work area.

The fire extinguishing system is only enabled when the work area door is closed.



If a fire extinguishing system is used, the ambient conditions for transport and storage of the machine are reduced to -10°C to +50°C.

DAA007EN - 2025-03-03 28 / 42



The fire extinguishing system allows the use of a water-based cooling lubricant with an oil content greater than 15% and cutting oil based on mineral oil.

The amount of cooling lubricant at the cutting edge must always be high enough to prevent the development of ignitable oil mists.

The cooling lubricant must have the following properties:

- Viscosity ≥ 10
- Flash point > 145°C
- Evaporation loss < 60%

Servicing should be carried out at regular intervals by qualified personnel according to the specifications of the manufacturer of the fire extinguishing system.

Push in the extinguishing opening (if there is one) only in case of fire. During operation, the opening must be closed. After the extinguishing process, the cover must be refitted.

5.3.2 Foreseeable misuse of the fire extinguishing system

The CO₂ fire extinguishing system is designed to extinguish fires involving flammable process materials such as coolant lubricants.

Alternative suitable measures, e.g., inert gas extinguishing systems, must be coordinated with the fire extinguishing system supplier when used in combination with flammable materials.

When combustible materials are used, other suitable measures must be taken to protect against fires and explosions.

5.4 Central extraction system

If the machine is connected to a central extraction system, the interaction with substances that are processed or used in other connected machines must be checked.

For assembly and tolerance reasons, a flexible pipe section is often installed between the central extraction system and the machine.

The flexible pipe section between the extraction system and the machine must be kept as short as possible and consist of fire-retardant or non-combustible material, due to the risk of fire.

DAA007EN - 2025-03-03 29 / 42



6 Safety instructions for different life phases

DANGER



Risk to life from falling loads

Falling loads can cause serious injury or death.

• Do not step under suspended or hanging loads.

Life phases:

- Transport and packing
- · Setup, installation, and commissioning
- Setup mode
- Operation (production mode)
- Maintenance, service, and repair
- Storage and decommissioning
- Disposal

6.1 Transport and packing

All covers and doors must be closed and secured.

The hydraulic system must be depressurized before transport. The vent hole in the hydraulic tank must be closed during transport (e.g., by a blanking plug).

Before transporting, the secure fastening of the batteries must be checked in the control cabinet.

Transporting the machine with the work area door open and tools mounted poses an increased risk of injury from protruding, sharp-edged tools. If necessary, the tools must be wrapped with a cloth or covered with protective sleeves.

The prescribed transport locks must be used. Only suitable, trouble-free transport means having sufficient load-carrying capacity may be used. Damaged transport means must not be used.

The transport means must be attached to the fastening points provided for this purpose. The cargo must be secured for transport with suitable lashing straps.

The machine must not be lifted at the control cabinet.

People must be kept away from beneath hanging or suspended loads.

Danger areas must be avoided, and the required safety distances must be observed when the machine is maneuvered/moved. The transport route must be kept free of obstacles and checked for levelness, floor damage, ascending or descending slopes, or similar.

The applicable rules and directives for air and sea transport must be observed.

6.2 Setup, installation, and commissioning

The load-carrying capacity of the floor must be observed. It must be chosen such that, when the machine is installed, the machine legs do not rest on openings in the floor (e.g., manhole covers), and there are no crushing or shearing points around the machine. The latter applies particularly to all movable parts of the machine (e.g., covers and doors). The required specifications can be found in the user documentation.

To avoid unintentional movements, the machine must be switched off before removing the transport locks.

DAA007EN - 2025-03-03 30 / 42



Any hydraulic, pneumatic, or electric lines or hoses damaged during transport must be replaced immediately. The hydraulic and cooling lubricant system must be checked (for leak tightness) before being switched on.

6.2.1 Electrical hazard due to potential difference



To reduce the contact voltage to a minimum, the individual components should be powered from the same energy source (transformer station), if possible.

To avoid potential differences from the machine to add-on components, such as cooling lubricant systems, bar feeders, tool magazines, robot cells, etc., the individual components are interconnected by equipotential bonding conductors. The machine forms the star point here.

Despite equipotential bonding, a contact voltage may occur between the individual components, especially if the components are powered by different energy sources.

6.3 Setup mode

Setup mode allows movements at reduced speeds with the work area door open, which may pose a certain risk. To reduce the risk, the following measures are required:

- The work area door should be kept closed as much as possible, especially during workpiece and tool movements.
- Avoid reaching into the work area when the spindle is rotating (max. rotational speed during setup mode is 50 rpm).
- The required personal protective equipment must be used, especially safety goggles.
- After setup is complete, the machine must be left in a state that allows it to start (or resume) production mode.

When the tailstock quill is actuated, there is a risk of injury from the travel movement of the quill tip. The use of a loading aid and wearing of protective gloves are recommended for manual tooling and when using a tailstock.

In case of a power supply failure, do not reach into the work area until all spindles, drives, and tool carriers have come to a halt.

If persons are accidentally trapped or restrained, observe the following:

- Locking in persons accidentally is impossible due to the design of the machine.
- Freeing trapped persons must be carried out by qualified personnel only, by traversing the corresponding NC axis, depending on the particular situation.
- Freeing trapped persons must take place by manual movement (using auxiliary equipment).

The instructions in the chapter **Changing tools** [22] also continue to apply.

6.4 Operation (production mode)

Operation of the machine requires a detailed analysis and assessment of the planned production process in terms of the risks and hazards that may be caused by it, such as the risks arising from the cooling lubricant or the material.

DAA007EN - 2025-03-03 31 / 42



- If non-combustible cooling lubricants are used in combination with non-combustible working materials, supervision of the machine is not required.
- The machine must be operated under supervision when using combustible cooling lubricants. A machine is considered to be sufficiently supervised if, for example, a person is present who can perceive the machine's fire extinguishing system's audible and visual alerts, or if activation of the fire extinguishing system is transmitted to a central monitoring location (e.g., a control center, fire department, etc.) and appropriate action can be taken on-site in response.

The machining sequence must be checked before starting the production (using a dry run).

The spray gun may only be used for cleaning workpieces and clamping devices. Always use appropriate protective equipment, especially safety goggles, during use. Use is only allowed with the work area door open.

Sufficient cooling of the entire machining process must be ensured.

Work in the work area must be carried out with the work area light switched on.

The work area light must be maintained in a clean condition to ensure safe working.

When the tailstock quill is actuated, there is an increased safety hazard from the travel movement of the quill tip. The use of a loading aid is recommended for manual tooling and when using a tailstock.

Do not reach between the pallets or workpieces during operation when using a workpiece feeder and discharge unit.

Chips may only be removed with suitable auxiliary equipment.

After every collision, the machine must be checked according to the instructions in the user documentation. When in doubt, the manufacturer should be consulted.

For machines with tool and workpiece magazines that can be entered, the machine must be switched off and locked out before troubleshooting any problems with the tool or workpiece logistics.

6.5 Maintenance, service, and repair

Maintenance and repair work is to be performed only by authorized and trained personnel. This applies particularly to work on motors (spindle motors) or other electrical assemblies. The instructions in the respective manufacturer documentation must be followed for such work.

We recommend the use of original spare parts and accessories. For damage caused by the use of parts from third-party providers, liability and warranty are excluded. The use of such products may change the structural characteristics of the machine and negatively affect active or passive safety.

Prior to working on the machine, it must be allowed to cool down, as hot parts may be located under the covers.

In general, maintenance and repair is to be carried out with the machine turned off. The main switch must be locked out.

Electrical components may carry electric energy even after the machine has been switched off. These components are identified with an information label and must not be touched before the specified discharging time has elapsed.

In a few cases, maintenance and repair need to be performed with the machine turned on (e.g., replacement of backup batteries). These activities must only be carried out by qualified personnel. The control system manufacturer's instructions must be observed.

Attach a warning sign on the operating terminal to prevent any actuation of switches or keys. Set up barriers to prevent access or interference by unauthorized persons.

DAA007EN - 2025-03-03 32 / 42



Fasteners must be loosened carefully and parts must be secured against falling down. When elastic items (springs) are removed/replaced, appropriate devices must be used. Any non-horizontal axes that pose a risk of falling down must be moved to their end positions or secured against falling down.

Pedal switches must be put aside to avoid inadvertent actuation.

For removing machine parts, suitable lifting devices must be used. Removed machine parts must be placed in a safe position and secured against falling over.

It may be necessary to remove or disable safety devices in order to carry out repairs. Any removed safety devices must be reinstalled immediately after finishing the repair.

When the control cabinet is open or the covers are open or removed, no cellular or wireless phones may be used within a 2 m radius.

For work on the hydraulic system, it must be depressurized by opening the accumulator drain valve(s).

Damaged hydraulic hose lines must be replaced immediately. Typical types of damage include chafing, kinks, cracks, deformations, or visible leaks.

The machine operator/owner is responsible for compliance with the laws and regulations of the country of use with regard to the use of hydraulic lines.

We recommend inspection and documentation of the hydraulic hose lines installed inside the machine and not directly visible every 12 months. For hydraulic hose lines which are visible in the work area or which are mounted outside the machine and which connect components to the machine, we recommend inspection and documentation every 6 months.

Flexible, pressurized hydraulic hose lines of INDEX/TRAUB equipment are generally thermoplastic or metal hydraulic hose lines.

For the flexible, pressurized hydraulic hose lines used by INDEX/TRAUB, empirical values are available for very different periods of use, some of which exceed 10 years.

If the machine has been disconnected from the power supply, the main switch must be switched off and locked out (e.g., using a padlock) before the power supply is reconnected.

After all maintenance and repair activities and work on electrical assemblies are finished, a dry run or functional test must be performed.

6.6 Storage and decommissioning

The following must be observed if the machine will not be used for an extended period of time:

- Move tool carriers to their lower end position..
- Switch off the machine and lock it out.
- Close and secure all covers and doors..

6.7 Disposal

For the disposal of the machine as well as machine parts, consumables, coolants, and operating fluids, the applicable regulations and directives must be observed.

The disposal may only be carried out by personnel trained for this purpose. If necessary, a specialist company must carry out the disposal.

DAA007EN - 2025-03-03 33 / 42



7 Product monitoring

We are committed to monitoring our products during their entire service life.

Therefore, we request that you notify us of any concerns related to the safety of the product. This applies also to necessary specifications that are not included in the documentation.

INDEX-Werke GmbH & Co. KG Hahn & Tessky

Plochinger Strasse 92

D-73730 Esslingen

Phone +49 711 3191-0

Fax +49 711 3191-587

info@index-werke.de www.index-group.com

DAA007EN - 2025-03-03 34 / 42



8 Declaration of conformity

The declaration of conformity is issued for each machine in accordance with the requirements of Directive 2006/42/EC Annex II and is provided to the customer as a separate document.

DAA007EN - 2025-03-03 35 / 42



9 Technical specifications

9.1 Approved ambient conditions

The following ambient conditions apply:					
Electromagnetic conditions	According to IEC 61000-6-2 and DIN EN 55011 (limit class A) $$				
Ambient temperature during transport and storage	-15°C to +55°C (up to +70°C for 24 hours)				
Ambient temperature at the place of use	10°C to 40°C				
Relative humidity	Condensation is not permitted.				
Maximum altitude:	1000 m above sea level				
If a fire extinguishing system is used: Ambient temperature for transport and storage of the machine	-10°C to +50°C				
Lighting conditions at the machine	According to DIN EN 12464				
No ionizing or non-ionizing radiation					
No explosion hazard in the environment					
Conductive grounding transitions less than 1 m tive touch panel	egaohm for optimum operation of the capaci-				

Contamination of the environment within the scope of the contamination caused by the machine itself

In the case of all optional components, the details in the purchased-part documentation must be observed.

9.2 Floor condition

The following conditions apply to the condition of the floor:

- Strong and vibration-free foundation
- Flatness deviations for finished floors according to DIN 18202

9.3 Noise emission

Valid: 01/2025.

Measured emitted sound pressure level LpA at the workplace (the operator's position):

Ready	ldling	Machining
	Emission sound pressure level LpA	
65	72	73
66	67	71
66	70	72
61	66	67
63	67	69
62	66	68
65	67	68
71	69	70
67	69	70
66	68	69
66	67	68
66	68	68
64	66	67
	65 66 66 61 63 62 65 71 67 66 66	Emission sound press 65 72 66 67 66 70 61 66 63 67 62 66 65 67 71 69 67 69 66 68 66 67 66 68

DAA007EN - 2025-03-03 36 / 42



Operating state of the machine	Ready	ldling	Machining
G500	65	67	68
G520	66	67	68
R200	65	71	73
R300	65	71	71
MS16-6	73	74	75
MS22-6	71	75	75
MS22-8	75	75	75
MS24-6	72	73	73
MS32-6	67	73	76
MS40-6	70	75	75
MS40-8	71	76	78
TNA400.2	66	68	72
TNA500	67	69	73
TNL12.2	67	68	69
TNL18	65	68	70
TNL20	68	68	68
TNL32	64	69	70
	Measur	ement uncertainty k	KpA in [dB]
All above-mentioned machines	4	4	4

The values when idling and machining were determined using the Index acceptance testing workpiece (with a special work cycle with machining according to ISO 8525).

The specified noise emission characteristics were determined according to ISO 230-5, incorporating ambient and room correction values.

According to DIN EN ISO 23125, we are required to issue the following statement:

"The values mentioned are emission levels and not necessarily safe working levels. Although there is a correlation between the degree of noise emission and the degree of noise pollution, it cannot be used reliably to determine whether additional protective measures are required or not. Among the factors that affect the actual noise level to which workers are exposed are the properties of the work area and other sources of noise, which is to say, the number of machines and other processes in the vicinity and the duration during which an operator is exposed to noise. In addition, the permissible exposure level may vary from country to country. However, this information should allow the user of the machine a better assessment of the hazards and risks."

DAA007EN - 2025-03-03 37 / 42



10 Safety instructions for machining workpieces and machining technologies



The general safety instructions in the chapters **Intended use of the machine** [▶ 10], **Work area enclosure and work area door** [▶ 16] and **Safety glass** [▶ 17] must be observed.

All dimensioning, specifications, and (safety) instructions, etc., are based on the machining of workpieces without unbalance, which are inherently stable, non-flammable, non-explosive, and non-hazardous to health.

If workpieces with deviating properties are to be machined, the operator/owner alone is responsible for taking supplementary measures to ensure the safe operation of the machine.

For example, when machining unbalanced or inherently unstable workpieces, the operator/owner must specify the maximum permissible spindle speed for the workpiece. The smaller of the two maximum speed limits of the clamping device or workpiece must be entered in the speed control (see also **Use and operation of clamping devices on the main and counter spindles [> 38]**).

A DANGER

Danger to life



The workpiece may be destroyed by overspeed.

Fragments, or the entire workpiece, can break through the work area enclosure

 Always enter the maximum speed limit in the speed monitoring function.

10.1 Use and operation of clamping devices on the main and counter spindles

Chucks used in INDEX or TRAUB machines must comply with the ISO 16156 or DIN EN 1550 standard (marked with maximum permissible speed, maximum permissible actuation force, and manufacturer's details).

The maximum speed indicated on the chuck (or other clamping devices) must be reentered into the speed monitoring function of the control system for each main and counter spindle at each job change (or change of clamping device).

A speed limit of the main and counter spindles secured by the control system can only be guaranteed if the permissible maximum spindle speed is correctly entered in the speed monitoring function.

The control system cannot guarantee beyond doubt that the speed specified in the NC program will be maintained. Even a speed limitation specified by the program (e.g., with command G92) is **not** safe.

A DANGER

Danger to life



The clamping device may be destroyed by overspeed.

Fragments of the clamping device, or the entire workpiece, can break through the work area enclosure.

• Always enter the maximum spindle speed in the speed monitoring function.

DAA007EN - 2025-03-03 38 / 42



In addition, the maximum permissible actuation force of the clamping device must be observed and complied with when setting the clamping force.

10.2 Use of tools in the motorized milling spindle

A maximum permissible speed must be entered in the tool data manager for each tool used in the motorized milling spindle.

A speed limitation secured by the control system can only be guaranteed if the maximum speed is set correctly for each individual tool.

△ DANGER

Danger to life



A tool can be destroyed by overspeed, or the machining tool can snap off due to unbalance.

The tool or the fragments can penetrate the work area enclosure.

 Always enter the maximum speed limit in the speed monitoring function

If a tool without maximum speed specification is used, the speed of the motorized milling spindle is automatically limited to 1000 rpm by the control system. This protection is removed by an input. Correctly specifying the maximum speed during the initial input is, therefore, crucial for speed limitation by the control system.

For tools for which no machining speed is provided or necessary in the motorized milling spindle, only a minimum maximum speed should be specified (e.g., "0" rpm or 1000 rpm).

10.3 Specific and individual single applications (of tools)

Highly specific single or individual machining operations (e.g., "reaming of holes" or "deep-hole drilling") can be applied on INDEX and TRAUB machines. In such applications, it may be necessary to provide the tool with a stabilizing guide through the hole to be machined for machining.

On the control/program side, it cannot be ensured that no speed or only a speed permissible for the free-running tool is output to the tool outside the hole to be machined.

⚠ DANGER

Danger to life



A tool can be destroyed or snap off at a speed outside the bore (even without overspeed).

The tool or the fragments can penetrate the work area enclosure.

• Observe the maximum speed limit.

10.4 Workpiece clamping with live center to improve workpiece quality

A live center unit on a turret (or the motorized milling spindle) is not a substitute for a full tailstock or tailstock function. The live center may only be used to improve the workpiece quality.

DAA007EN - 2025-03-03 39 / 42



 \int_{1}^{∞}

Secure clamping of the workpiece must be ensured by the clamping in the main and counter spindles alone.

▲ DANGER

Danger to life



In the event of power failures, it cannot be ensured that the live center will remain in the center of the workpiece.

If the workpiece clamping is lost, the workpiece can be ejected and penetrate the work area enclosure!

• Keep your distance!

10.5 Safe workpiece clamping using the tailstock or tailstock function

If a workpiece can only be held in the workpiece clamping device by using a tailstock (or the tailstock function), the tailstock or the tailstock function serves to secure the clamping.

The tailstock (or tailstock function) must never be removed from the spinning workpiece during the program run (or manually). Without a set tailstock (or tailstock function), a speed may not be programmed or manually set on the main and counter spindles.

The control system/program cannot ensure that no speed or only a speed permissible for the workpiece without tailstock (function) is output at the main spindle and counter spindle if the tailstock is not attached or if the tailstock function is not active.

A DANGER

Danger to life



If the workpiece clamping is lost, the workpiece can be ejected and penetrate the work area enclosure!

• Keep your distance!

10.6 Workpiece clamping with a steady rest to improve workpiece quality

If a steady rest on a tool carrier or steady rest slide is only temporarily used on the workpiece in the program and optionally removed from the workpiece, the steady rest may only be used to improve the workpiece quality.

Secure clamping of the workpiece must be ensured by the clamping in the main and counter spindles alone.

The control system/program cannot ensure that no speed or only a speed permissible for the workpiece is output at the main and counter spindles when the steady rest is open or removed.

▲ DANGER

Danger to life



If the workpiece clamping is lost, the workpiece can be ejected and penetrate the work area enclosure!

Keep your distance!

DAA007EN - 2025-03-03 40 / 42



10.7 Safe workpiece clamping with steady rest

If a workpiece can only be held in the workpiece clamping device by using a steady rest on a tool carrier or steady rest slide, the steady rest serves to secure the clamping.

The steady rest must never be opened (under speed) in the program, removed from the workpiece during the program run, or manually. Never program or manually preset a speed on the main and counter spindles when they are open or removed.

On the control/program side, it cannot be ensured that when the steady rest is open or removed, no speed or only a speed permissible for the workpiece without steady rest or steady rest slide is output at the main and counter spindle.

A DANGER

Danger to life



If the workpiece clamping is lost, the workpiece can be ejected and penetrate the work area enclosure!

• Keep your distance!

10.8 Use of clamping devices with several workpiece clamping options on main and counter spindles

To be able to machine workpieces (e.g., shafts) completely automatically, special chucks with several workpiece clamping options (e.g., double piston clamping cylinders) are used on INDEX and TRAUB machines.

The workpiece clamping options are controlled (programmed) directly from the program to press on, close, or open a different workpiece clamping type (e.g., axial or radial).

The programmer or operator/owner must ensure that safe clamping of the workpiece on the main and counter spindles is ensured at all times during the program run or any manual intervention. The sequence of workpiece clamping must be programmed accordingly.

In particular, it must be ensured that none of the workpiece clamping devices acts against the safe workpiece clamping on the main and counter spindles and cancels them or even pushes them out of the workpiece clamping device.

The control system/program cannot ensure that in the event of insufficient workpiece clamping, no speed or only a speed permissible for the reduced workpiece clamping is output for the workpiece on the main and counter spindles.

⚠ DANGER

Danger to life



If the workpiece clamping is lost, the workpiece can be ejected and penetrate the work area enclosure!

Keep your distance!

DAA007EN - 2025-03-03 41 / 42



INDEX-Werke GmbH & Co. KG Hahn & Tessky

Plochinger Straße 92 D-73730 Esslingen

Fon +49 711 3191-0 Fax +49 711 3191-587

info@index-werke.de www.index-group.com